

## **CHANGE HISTORY for**

- ✓ **AVIC-F900BT**
- ✓ **AVIC-F9110BT**

### **Ver. 2.009000**

- Improvement of system stability (fixing "file crash" error, rebooting, etc.)
- Dummy file has been added to APL3 folder as some decompression software can not decompress empty folders
- Auto file correction has been added for the setting file to prevent that the file becomes corrupt

### **Ver. 2.007000**

- Solved problem on Polish on-screen keyboard
- Solved reboot problem after receiving specific TMC data in Germany (area information is displayed correctly)
- Improvement of system stability.

### **Ver. 2.005000**

- Solved reboot problem after receiving specific TMC data in Germany

### **Ver. 2.001000**

- Increased the Microphone sensitivity for Bluetooth

### **Ver. 1.900000**

- Substantial reduction in System Startup Time
- Improved Touch Panel Response
- Increased maximum display brightness
- Support for Phonebook Tags (Home - Work - Office-)in the Contacts menu

### **Ver. 1.002000**

- Possible reboot when performing UK address search.

### **Ver. 1.001900**

- Polish/Czech/Turkish/Croatian/Romanian language corrections.
- Improved compatibility with iPod Touch (software version 2.0).
- Changed default setting of Speed Limit Warning / Dynamic Volume Setting
- TTS voice guidance quality improvement



**Ver. 1.001600**

- Sporadic volume increase when playing MP3 files stored on USB stick /SD memory card
- Sound skipping of MP3 files during route guidance
- Bluetooth Hands-Free sound quality improvement
- TTS voice guidance quality improvement
- System stability while updating